

Message Text

UNCLASSIFIED

PAGE 01 PRETOR 03557 270522Z
ACTION STE-01

INFO OCT-01 AF-10 ISO-00 OC-06 CCO-00 SY-05 DRC-01
/024 W

-----050220 270532Z /17/53

P 261055Z JUN 78
FM AMEMBASSY PRETORIA
TO SECSTATE WASHDC PRIORITY 1481

UNCLAS PRETORIA 3557

C O R R E C T E D C O P Y (C A P T I O N ; T A G S)

FOR OPR/ST, INFO OC/S AND SY

E.O. 11652: N/A
TAGS: ASUP ASEC AFAC
SUBJECT: MODIFIED IBM SELECTRIC II TYPEWRITERS

1. POST IS EXPERIENCING A MULTITUDE OF OPERATING PROBLEMS, BOTH MECHANICAL AND ELECTRICAL, WITH ALL OF THE FIFTEEN (15) SELECTRICS ORDERED ON 31 OCT 77, ORDER NO. 5584-871002. ALL MACHINES, EITHER MODIFIED OR NOT, WHEN USED DAILY ARE SUBJECT TO MOTOR OVERHEATING AND A EXCESS OF MECHANICAL PROBLEMS. THE LOCAL IBM REPRESENTATIVE, WHO INSTALLED THE MODIFICATION PACKS, INDICATED THAT: (A) THE TYPEWRITER MOTORS SHOULD BE SPECIFICALLY ORDERED FOR USE WITH THE 250 VOLT 50 HZL ELECTRICAL SYSTEM IN PRETORIA. (B) THE HEAVY FLYWHEEL USED ON THE MODIFIED MOTOR WILL ULTIMATELY LEAD TO MOTOR BEARING FAILURE. (C) THE MOTOR (BOTH FOR THE MODIFIED AND UNMODIFIED) DOES NOT HAVE SUFFICIENT POWER/TORQUE TO OPERATE THE MECHANICAL COMPONENTS OF THE TYPEWRITER FOR EXTENDED PERIODS OF TIME WITH THE LOCAL POWER SOURCE.

2. POST HAS RECEIVED ALL OF THE FIFTEEN MODIFICATION KITS. HOWEVER, FOUR OF THESE MOTORS WERE UNCLASSIFIED

UNCLASSIFIED

PAGE 02 PRETOR 03557 270522Z

RECEIVED WITH BENT MOTOR SHAFTS, MAKING THE MODIFICATION OF THE TYPEWRITER UNFEASIBLE. POST WILL BE RETURNING THESE MOTORS TO OPR/ST VIA REGISTERED AIR POUCH.

3. POST WOULD APPRECIATE ANY TECHNICAL ADVICE TO HELP ELIMINATE THESE MOST IRRITATING PROBLEMS. POST WILL FIND IT NECESSARY TO UTILIZE OLD MACHINES, OR

PURCHASE IBM SELECTRICS LOCALLY, IF THESE PROBLEMS
CONTINUE.

4. POST HAS ORDERED FIVE (5) NEW IBM SELECTRICS,
WITH VENDOR INSTALLED MODIFICATION PACKS,
ON 6/20/78, REQUISITION NO. 5584-871019. THIS REQUISITION
SPECIFICALLY CALLS FOR MOTORS THAT ARE 250 VOLT 50 HZ.
IF VENDOR UNABLE TO MEET WITH THIS REQUEST PLEASE ADVISE
ASAP.
EDMONDSON

NOTE BY OC/T: DISTRIBUTIONS TO OC, CCO AND SY TAKE FOR FIRST TIME.

UNCLASSIFIED

NNN

Message Attributes

Automatic Decaptoning: X
Capture Date: 01 jan 1994
Channel Indicators: n/a
Current Classification: UNCLASSIFIED
Concepts: n/a
Control Number: n/a
Copy: SINGLE
Draft Date: 26 jun 1978
Decaption Date: 01 jan 1960
Decaption Note:
Disposition Action: n/a
Disposition Approved on Date:
Disposition Case Number: n/a
Disposition Comment:
Disposition Date: 01 jan 1960
Disposition Event:
Disposition History: n/a
Disposition Reason:
Disposition Remarks:
Document Number: 1978PRETOR03557
Document Source: CORE
Document Unique ID: 00
Drafter: n/a
Enclosure: n/a
Executive Order: N/A
Errors: N/A
Expiration:
Film Number: D780267-0916
Format: TEL
From: PRETORIA
Handling Restrictions: n/a
Image Path:
ISecure: 1
Legacy Key: link1978/newtext/t19780620/aaaaarcz.tel
Line Count: 74
Litigation Code IDs:
Litigation Codes:
Litigation History:
Locator: TEXT ON-LINE, ON MICROFILM
Message ID: 3114ee7f-c288-dd11-92da-001cc4696bcc
Office: ACTION STE
Original Classification: UNCLASSIFIED
Original Handling Restrictions: n/a
Original Previous Classification: n/a
Original Previous Handling Restrictions: n/a
Page Count: 2
Previous Channel Indicators: n/a
Previous Classification: n/a
Previous Handling Restrictions: n/a
Reference: n/a
Retention: 0
Review Action: RELEASED, APPROVED
Review Content Flags:
Review Date: 13 apr 2005
Review Event:
Review Exemptions: n/a
Review Media Identifier:
Review Release Date: n/a
Review Release Event: n/a
Review Transfer Date:
Review Withdrawn Fields: n/a
SAS ID: 2209381
Secure: OPEN
Status: NATIVE
Subject: MODIFIED IBM SELECTRIC II TYPEWRITERS
TAGS: ASUP, ASEC, AFAC
To: STATE
Type: TE
vdkgvgwkey: odbc://SAS/SAS.dbo.SAS_Docs/3114ee7f-c288-dd11-92da-001cc4696bcc
Review Markings:
Sheryl P. Walter
Declassified/Released
US Department of State
EO Systematic Review
20 Mar 2014
Markings: Sheryl P. Walter Declassified/Released US Department of State EO Systematic Review 20 Mar 2014